

Top 20 Deficiencies Reported with Largest Deviations in last 3 years (2015 - 2017)

| S. No. | Deficiency Code | Deficiency Name | 2015 | 2016 | 2017 |
|--------|-----------------|---|------|------|------|
| 1 | 07199 | Other (fire safety) | 464 | 400 | 293 |
| 2 | 10116 | Nautical publications | 325 | 429 | 277 |
| 3 | 10111 | Charts | 314 | 256 | 168 |
| 4 | 11131 | On board training and instructions | 239 | 287 | 181 |
| 5 | 10112 | Electronic charts (ECDIS) | 68 | 132 | 161 |
| 6 | 01199 | Other (certificates) | 107 | 191 | 185 |
| 7 | 11101 | Lifeboats | 315 | 340 | 259 |
| 8 | 15106 | Shipboard operations | 165 | 228 | 148 |
| 9 | 10127 | Voyage or passage plan | 299 | 269 | 222 |
| 10 | 04110 | Abandon ship drills | 174 | 150 | 103 |
| 11 | 07109 | Fixed fire extinguishing installation | 160 | 137 | 93 |
| 12 | 01308 | Records of rest | 254 | 218 | 189 |
| 13 | 07126 | Oil accumulation in engine room | 62 | 73 | 125 |
| 14 | 04118 | Enclosed space entry and rescue drills | 87 | 26 | 44 |
| 15 | 05110 | Facilities for reception of marine safety inform. | 171 | 166 | 111 |
| 16 | 11104 | Rescue boats | 83 | 112 | 139 |
| 17 | 01214 | Endorsement by Flag State | 76 | 119 | 64 |
| 18 | 07105 | Fire doors/openings in fire-resisting divisions | 227 | 239 | 187 |
| 19 | 11112 | Launching arrangements for survival craft | 87 | 97 | 45 |
| 20 | 10106 | Compass correction log | 111 | 82 | 60 |

