

Top 5 Deficiencies Reported (2018-2022)

Year	Deficiency	No. of Deficiencies	Deficiency %age
2022	Other (fire safety) (07199)	328	3.31%
	Other (machinery) (13199)	265	2.68%
	Oil accumulation in engine room (07126)	207	2.09%
	Fire-dampers (07115)	194	1.96%
	Lifeboats (11101)	192	1.94%
	Total Deficiencies : 9902		
2021	Other (fire safety) (07199)	270	2.96%
	Other (machinery) (13199)	229	2.51%
	Lifeboats (11101)	202	2.21%
	Fire doors/openings in fire resisting divisions (07105)	173	1.89%
	Emergency, lighting, batteries and switches (04103)	173	1.89%
	Total Deficiencies : 9131		
2020	Other (fire safety) (07199)	285	3.07%
	Other (machinery) (13199)	235	2.53%
	Lifeboats (11101)	204	2.20%
	Other (Conditions of employment) (18299)	172	1.85%
	Lights, shapes, sound-signals (10109)	166	1.79%
	Total Deficiencies : 9288		
2019	Lifeboats (11101)	267	2.44%
	Other (fire safety) (07199)	264	2.41%
	Other (machinery) (13199)	240	2.19%
	Ventilators, air pipes, casings (03108)	209	1.91%
	Emergency, lighting, batteries and switches (04103)	197	1.8%
	Total Deficiencies : 10960		
2018	Other (machinery) (13199)	301	2.54%
	Nautical publications (10116)	264	2.23%
	Lifeboats (11101)	243	2.05%
	Other (fire safety) (07199)	225	1.90%
	Emergency, lighting, batteries and switches (04103)	212	1.79%
	Total Deficiencies : 11847		